

Location	Road Name	Request	Comments	Category
Speed	Cook Road	Upgrade to All weather access road	Patched Done and Completed	RA5
Speed	Tempy Nandaly Road	Grading Required east of Pirro SBR	Completed maintenance grading in February	RC2
Lascalles	Wathe Reserve Road	New House - formed road only - gravel road request	Completed	RA4
Woomelang	Kellys Road	Gravel resheet - on CWP 2022/23	Completed	RA2
Yaapeet	Fields Road	Requires Grading	Completed	RA5
Yaapeet	Yaapeet South Road	Gravel Resheets - check conditions	Completed	RA5
Yaapeet	Yaapeet North Road	Yaapeet North Road and Hopetoun Yaapeet Road Hotmix top up	Completed	RA2
Yaapeet	Gaalanungah North Road	Gravel Resheet	Completed	RA5
Yaapeet	Whites Road	Gravel Patching required, drainage issues	Grading Works Completed	RA5
Hopetoun	Kinkora Road	Gravel Grading requires throughout the length	Resheet Completed	RA2
Hopetoun	Moyles Road	Inspection required for gravel patching	Completed	RA5
Hopetoun	Crows Road	Require Grading Plus maintenance	Completed	RA5
Beulah	Boundary Road	Poor Gravel Section on South and North side of Brentwood west rd	Completed	RC2
Beulah	Golf Hill Road	Slippery, poor material , requires maintenance	Resheet Done	RA2
Beulah	Maroski Road	Gravel Resheet	Completed CWP 22/23	RA5
Brim	Fryatt Road	Rough Surface - Check Condition, grading required	Completed	RA4
Brim	Brennans Road	Grading Required, Poor Drainage	Completed	RA2
Brim	Quicks Road	Quicks Rd and Brim West Road Intersection - Severe edge drop off	Completed	RA2
Brim	Brim West Road	Consider Shoulder Widening for truck passing at higher speed, and advisory signs of 80km/hr	Completed	RC1
Brim	Quicks Road	Drainage Issues	Completed	RA5
Brim	Golders Road	Grading Required	Completed	RA2
Brim	Sturrocks Road	Grading and Drainage Issue	Completed	RA5
Sheep Hills	SHeep Hills Intersection	Danger Intersection, near misses, vehicles turning using left slips	Completed	RC1
Lubeck	Hoods Road	Drainage issues between Horsham Lubeck and Gellatlys Road	Completed	RA5
Wallup	Ailsa Road	Grading Request	Completed	RA5